

To: Hanson, Kristen[KHanson@ldftribe.com]; Sharp-Dahl, Julie[jsharp-dahl@bristol-companies.com]
From: Egan, Robert
Sent: Mon 12/29/2014 6:05:18 PM
Subject: RE: Tower Standard tap water data

Thanks.

I will send the results to my supervisor so we can discuss here, and then we should have a call sometime in the next week or so if that fits your schedule.

Bob Egan

Corrective Action Manager

Underground Storage Tanks Section

RCRA Branch

(312) 886-6212

(312) 692-2911 (fax)

From: Hanson, Kristen [mailto:KHanson@ldftribe.com]
Sent: Monday, December 29, 2014 12:02 PM
To: Egan, Robert; Sharp-Dahl, Julie
Subject: RE: Tower Standard tap water data

Sure Bob,

The Burman Residence is the closest well to the site on the East side of the lake. The sampling point is in a closet between the entry porch and the house.

Kristen

From: Egan, Robert [<mailto:egan.robert@epa.gov>]
Sent: Monday, December 29, 2014 12:00 PM
To: Hanson, Kristen; Sharp-Dahl, Julie
Subject: RE: Tower Standard tap water data

Thank you, Kristen.

Can you tell me which location that is on the lake? I know these are below the method detection limit but we should discuss this after I get a chance to check the screening levels.

Nothing to be alarmed about at this time. It will be interesting to see what the next sample results show.

Bob Egan

Corrective Action Manager

Underground Storage Tanks Section

RCRA Branch

(312) 886-6212

(312) 692-2911 (fax)

From: Hanson, Kristen [<mailto:KHanson@ldftribe.com>]
Sent: Monday, December 29, 2014 11:57 AM
To: Egan, Robert; Sharp-Dahl, Julie
Subject: RE: Tower Standard tap water data

I believe it is Burmans.

From: Egan, Robert [<mailto:egan.robert@epa.gov>]
Sent: Monday, December 29, 2014 11:56 AM
To: Sharp-Dahl, Julie; Hanson, Kristen
Subject: RE: Tower Standard tap water data

Julie,

Can you coordinate the sample that had the xylene hits to an address?

Thanks.

Bob Egan

Corrective Action Manager

Underground Storage Tanks Section

RCRA Branch

(312) 886-6212

(312) 692-2911 (fax)

From: Sharp-Dahl, Julie [<mailto:jsharp-dahl@bristol-companies.com>]
Sent: Monday, December 29, 2014 10:50 AM
To: KHanson@ldftribe.com; Egan, Robert
Subject: Tower Standard tap water data

Hi Kristen,

I received your call regarding the analytical results for the three tap water samples you submitted for us.

Attached are the analytical results. The "J" flag adjacent a results means that the result is an estimated value and the "B" means the result may be elevated due to method blank contamination.

Please email or call if you have questions. Thank you again Kristen for your help.

I hope you have a Happy New Year!

Julie Sharp-Dahl
Senior Project Manager
Bristol Environmental Remediation Services, LLC
111 W. 16th Avenue, Third Floor
Anchorage, AK 99501-5109
Phone : (907) 743-9394
FAX : (907) 563-6713
jsharp-dahl@bristol-companies.com
<http://www.bristol-companies.com/>

CONFIDENTIAL NOTICE: This document is for the sole purpose of the intended recipient(s) and may contain confidential and privileged information. Any unauthorized review, use, disclosure, or distribution is prohibited. If you are not the intended recipient, please contact the sender and destroy all copies of the original document.

--